

Directions for use:

Spa Oxidizing Shock

Read entire label before using

NCI threaded safety cap = 1/2oz

NCI large over cap = 5oz

Initial Treatment

Add 2oz per 300 gallons (1135L) of spa water

Regular Treatment

- After each time the spa is used, add 1oz per 300 gallons (1135L) of water
- Add 1oz per 300 gallons (1135L) each week the spa is not being used
- Add product with circulating pump running, continue circulating for at least 30 minutes
- Turn the jets on and off once or twice after adding the product to improve the treatment